


**Appendix 1:**



If 110°C load chart is selected Pasha Balloons highly recommend smooth maneuvering and the use of an electronic envelope temperature sensor.  
As Pasha Balloons AFM indicates, 120°C must not be exceeded in any circumstances.